

INTERCOMPANY CORRESPONDENCE

National
Linen
Service



RECEIVED
N.C. Dept. N...

NOV 2 1990

Winston-Salem
Regional Office

DATE: 30 Oct 1990
TO: Mr Tom Salley
SUBJECT: Under Ground Storage Tanks

FROM: Ronald Belcher
Plant Engineer
National Linen Service

Dear Mr Salley

On 8 Oct 1990 we at National Linen Service 201 S Stratford Rd had our under ground fuel storage tanks tested by Environmental Resource Center of Fayetteville N.C. to meet EPA criteria for tight tank systems, the unleaded tank didnot meet the criteria for a tight system, the product level in the fill pipe above 8 inches could not be maintained.

The suction and vent lines to the unleaded tank were uncovered and a leak was found in the 2 inch vent line, the leak was repaired and the tank retested 10 Oct 1990 by Environmental Resource Center and found to be tight at 25 inches above tank top.

Soil samples at the leak and on both sides of the tank were sent to Research and Analytical Laboratories Inc to be tested for hydrocarbons/gasoline, the results of the tests were less than 10 PPM hydrocarbons/gasoline.

Sincerely

Ronald Belcher
Plant Engineer
National Linen Service



RESEARCH & ANALYTICAL LABORATORIES, INC.

Analytical/Process Consultations

10 CERT #34

NATIONAL LINEN
201 S. STRATFORD ROAD
WINSTON-SALEM, NC 27103
Attn:

Date Sample Collected : 10/08/90
Date Sample Received : 10/08/90
Date Sample Analyzed : 10/06/90
Date of Report : 10/20/90

Analyses Performed by : SC

Job Number : 00439 K

Lab Sample Number

91342

Parameter	Storet #	Results
Hydrocarbons/Gasoline		<10 PPM

EPA Method 5030

Clients Sample Source/Number : BACK SIDE OF TANK



RESEARCH & ANALYTICAL LABORATORIES, INC.

Analytical/Process Consultations

NC CERT #34

NATIONAL LINEN
201 S. STRATFORD ROAD
WINSTON-SALEM, NC 27103
Attn:

Date Sample Collected : 10/08/90
Date Sample Received : 10/08/90
Date Sample Analyzed : 10/06/90
Date of Report : 10/20/90

Analyses Performed by : SC

Job Number : 00439 K

Lab Sample Number

91341

Parameter	Storet #	Results
Hydrocarbons/Gasoline		<10 PPM

EPA Method 5030

Clients Sample Source/Number : RIGHT SIDE OF LEAK



RESEARCH & ANALYTICAL LABORATORIES, INC.

Analytical/Process Consultations

NC CERT #34

NATIONAL LINEN
201 S. STRATFORD ROAD
WINSTON-SALEM, NC 27103
Attn:

Date Sample Collected : 10/08/90
Date Sample Received : 10/08/90
Date Sample Analyzed : 10/06/90
Date of Report : 10/20/90

Analyses Performed by : SC

Job Number : 00439 K

Lab Sample Number

91340

Parameter	Storet #	Results
Hydrocarbons/Gasoline		<10 PPM

EPA Method 5030

Clients Sample Source/Number : LEFT SIDE OF LEAK